

## HOLYHEAD – LOCAL NOTICE TO MARINERS 06/2026

### Terminal 5 Turning and Berth Line Fender

Issued: 1<sup>st</sup> January, 2025

Mariners are advised that Terminal 5 dolphin 5F turning and berth line fenders have been removed leaving the pile and concrete structure exposed.



Mariners are also reminded that due to previous damage Terminal 3 dolphin D9 turning fenders are also out of service.

A notice will be issued when the fenders are back in commission.

John Goddard  
Harbour Master